


**ANNEXURE C**  
**PROFORMA FOR SAFE DRINKING WATER AND SANITARY  
CONDITION CERTIFICATE**

**No. AEE/RDWS&S/S.Dn/Blre/East/641/2024-25**

**Date: 24/01/2025**

It is certified that an inspection team headed by SRINIVASU .T Assistant Executive Engineer and NAVEENA C. Assistant Engineer from Rural Drinking Water Supply and Sanitation Sub Division Bangalore East Taluk, K.R.Puram-560036 . Inspected the East Bangalore School, No.76/2, Gundur Village, Bidarahalli Hobli, Virgonagara Post, Bangalore-560049. On 23/01/2025 and Found that the the East Bangalore School, has safe drinking water facilities for the students and members of staff of the institution. School is also Maintains the hygienic sanitation condition in the school building and the campus as per norms prescribed by the Central/State/U.T. Govt. The Above is Valied for a Period of One Year from date of Issue of the same.

  
**Assistant Executive Engineer**  
**R D W & S Sub Division,**  
**to Bangalore East Taluk.**

**Name : SRI. SRINIVASU .T**

**Designation : Assistant Executive Engineer.**

**Name & Address of the office/Department:**

**Assistant Executive Engineer Office**

**The Rural Drinking Water Supply and Sanitation Sub Division**

**Bangalore East Taluk, K.R.Puram-560036**

**To:**

**Sri. Naveen G.S**

**Chairman**

**East Bangalore School,**

**No.76/2, Gundur Village,**

**Bidarahalli Hobli, Virgonagara Post,**

**Bangalore-560049.**